

Category of work: REMODELING Contractor: LAGINA BUILDERS & REMODELERS

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: MAY THROUGH SEPTEMBER

Description of Work: ALL NEW WINDOWS & DOORS. NEWSIDING ON FRONT WALL. ALL NEW INSULATION, ELECTRIC, PLUMBING HEATING & COOLING, DRY WALL & WOODWORK, FLOOR COVERING, KITCHEN CABINETS & COUNTERS. IN LIVING AREA

Address where work done: _____ (optional)

Name of Company: LAGINA BUILDERS Phone: (440) 342-2014

Contractor's Name: MICHAEL LAGINA

Street Address: 5080 LEARNAGEL

City/Zip: NORTH RIDGEVILLE, OH 44039

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	<input checked="" type="checkbox"/>		
On quality of work	<input checked="" type="checkbox"/>		
On starting when promised	<input checked="" type="checkbox"/>		
On completing once started	<input checked="" type="checkbox"/>		
On fixing problems, if any	<input checked="" type="checkbox"/>		

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work – Explanation of Problems – Suggestions to Others

NICE NEAT WORK. I THINK A REAL DESIRE TO DO A GOOD JOB.

Source used to find contractor: MY WIFE'S SON

What was the total cost of work done: ABOUT \$70,000.00

(OVER)

Category of work: Bathroom Remodel Contractor: Pride Remodeling Co. 201

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: March 2011

Description of Work: New Tub Surround, Re-Glaze Tub, New Faucets/Fixtures
New Linoleum/Floor, Paint
- New Back/Outside Stairs

Address where work done: _____ (optional)

Name of Company: Pride Remodeling Phone: 440-885-3086

Contractor's Name: Paul Ziemski

Street Address: Just moved

City/Zip: _____

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	X		
On quality of work	X		
On starting when promised	X		
On completing once started	X		
On fixing problems, if any	X		

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work – Explanation of Problems – Suggestions to Others

Paul has done work on our home at 1284 Donald Ave
since 1993. Work has included total Bathroom/kitchen demolition
Remodel, New Garage & 4 new windows

Suggestion: Get an estimate from Pride

Source used to find contractor: 1993- Lakewood Sun Post

What was the total cost of work done: \$10,000

(OVER)

AIR CONDITION WHOLE HOUSE
NEW KITCHEN

Category of work: RADIANT HEAT Contractor: DASO CABINETRY & REMODEL ²⁰⁸

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: 5-18-11

Description of Work: REMOVE KITCHEN TO STUDS. NEW PLUMBING IN 2 BATHS (up) + KITCHEN. NEW WIRING IN KITCHEN. RAISED CEILING. NEW FLOOR, CUSTOM CABINETRY & TRIM.

Address where work done _____ (optional)
 Name of Company: DASO CABINETRY & REMODELING Phone: 330-738-7740
 Contractor's Name: JEFF DASO
 Street Address: 196 E. WEST SALEM
 City/Zip: PRESTON Ohio 44217

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid		✓	
On quality of work	✓		
On starting when promised	✓		
On completing once started		✓	
On fixing problems, if any	✓		

Were there unexpected costs (i.e., was "additional" work needed?) yes no
 - Had contractor warned you in advance of the possibility? yes no
 - Were the costs fair/reasonable? yes no

Comments on Work - Explanation of Problems - Suggestions to Others

DASO WORKED very hard to please & Do a good job. The GRANITE SUB-CONTRACTOR WAS NOT AS CONCERNED & CAUSED 6WK DELAY

Source used to find contractor: HOME SHOW

What was the total cost of work done: _____

(OVER)