

103

REBUILD BRICK STAIRS/OUTDOORS Contractor: R.G. MASONRY

RON GEORGE

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? [x] yes [ ] no [ ] see comments

Date of Work: FALL 2010

Description of Work: EXTERIOR FRONT BRICK STAIRS REBUILT w/ SANDSTONE TREADS (RE-USE OF OLD TREADS); MISCELLANEOUS TUCK POINTING ON HOME EXTERIOR

Address where work done: \_\_\_\_\_ (optional)

Name of Company: R.G. MASONRY Phone: 214 226 8808

Contractor's Name: RON GEORGE

Street Address: 1420 WESTWOOD AVE

City/Zip: GAREWOOD OH 44107

Please rate your contractor/service in making the repair:

Table with 4 columns: Rating (Very Good, Average, Poor) and 5 rows of repair tasks with checkmarks in the Very Good column.

Were there unexpected costs (i.e., was "additional" work needed?) [x] yes [ ] no

- Had contractor warned you in advance of the possibility? [x] yes [ ] no

- Were the costs fair/reasonable? [x] yes [ ] no

Comments on Work - Explanation of Problems - Suggestions to Others

RON HAS YEARS OF EXPERIENCE IN MASONRY, VERY KNOWLEDGEABLE WHEN IT COMES TO OLDER STRUCTURES. HE PERSONALLY PERFORMS THE WORK AND KEEPS YOU ABREAST OF ANY ISSUES THAT MAY ARISE ON THE PROJECT. EASY TO WORK WITH AND VERY PROFESSIONAL AND CONSCIENTIOUS. CLEAN WORK AREA ALSO.

Source used to find contractor: neighborhood list

What was the total cost of work done: \$6,000.00

(OVER)