

Plaster/Drywall (77)

Category of work: REPAIR STORM DAMAGE Contractor: DANE CONTRACTORS - WESTLAKE, OHIO

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: 5/10 THROUGH 11/10

Description of Work: SEE ATTACHED PICS

Address where work done: LEWIS - ..., LEWISWOOD, OH (optional)

Name of Company: DANE CONTRACTORS Phone: 440-617-5800

Contractor's Name: DON NIGRO, PRESIDENT

Street Address: 1080 BASSETT ROAD

City/Zip: WESTLAKE, OHIO

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	✓		
On quality of work	✓		
On starting when promised	✓		
On completing once started	✓		
On fixing problems, if any	✓		

Were there unexpected costs (i.e., was "additional" work needed?) yes no **UNEXPECTED COSTS**

- Had contractor warned you in advance of the possibility? yes no **TOTALLY NORMAL IN**

- Were the costs fair/reasonable? yes no **A STORM DAMAGE SITUATION**

Comments on Work - Explanation of Problems - Suggestions to Others

DANE WAS GENERAL CONTRACTOR, FOLLOWING ARE

AMONG THE SUB-CONTRACTORS PROVIDING QUALITY WORK!

HAYWOOD ELECTRIC A1 PLASTERING

S. BRADLEY ROOFING CHIMNEY + MASONRY COMPANY

BAY HEATING HOME WORKS

Source used to find contractor: INSURANCE AGENT

What was the total cost of work done: \$ 200,000 +