

Category of work: _____ Contractor: Greg Allen Builders, Inc.



Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: May - August 2010

Description of Work: Wind storm damage repair - replace exterior siding, windows, downspouts and roof repair. Install new kitchen and laundry room renovation (new cabinets and counters).

Address where work done: _____ (optional)

Name of Company: Greg Allen Builders, Inc. Phone: 440-871-7013

Contractor's Name: Greg Allen

Street Address: 3888 Long Road

City/Zip: AVON 44011

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	✓		
On quality of work	✓		
On starting when promised	✓		
On completing once started	✓		
On fixing problems, if any	✓		

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work - Explanation of Problems - Suggestions to Others

High quality work. Contractor's employees were very responsive to requests, very pleasant and very professional. Definitely will hire again.

Source used to find contractor: Neighbors

What was the total cost of work done: \$40,000.00

Category of work: Home Siding and windows Contractor: Airko / Mark Gilbert

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: Spring 2010

Description of Work: Did siding. Looks wonderful - windows are all I expected. Very good.

Address where work done: _____ (optional)

Name of Company: Airko Phone: 440 333-0133

Contractor's Name: Mark Gilbert

Street Address: 20160 Centur Ridge Road

City/Zip: Rocky River, Ohio

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	<input checked="" type="checkbox"/>		
On quality of work	<input checked="" type="checkbox"/>		
On starting when promised	<input checked="" type="checkbox"/>		
On completing once started	<input checked="" type="checkbox"/>		
On fixing problems, if any <u>but waiting for a small item</u>	<input checked="" type="checkbox"/>		

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work - Explanation of Problems - Suggestions to Others

This is a good company - quality product.

Source used to find contractor: Friend @ work I have recommended Airko to friends & co-workers.

21

NEW ELECTRIC
PLUMBING AND AIR.C.
WINDOWS

DEPENDABLE ELECTRIC
POMPELLI PLUMBING + AIR COND
STANEK WINDOWS

Category of work: _____ Contractor: _____

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes **X3** no see comments

Date of Work: MAY - JUNE 2010

Description of Work: ELECTRIC - NEW PANEL / EXTERIOR METER
REPLACE WIRING + OUTLETS 'ADD GFI TO KITCH' + BATH
PLUMBING - PUT WASHER / DRYER SERVICE IN KITCHEN
REPLACED FIXTURES IN BATHROOM
WINDOWS - REPLACED ALL 32 WINDOWS

Address where work done: _____ optional

Name of Company: DEPENDABLE ELECTRIC
POMPELLI PLUMBING STANEK WINDOWS

Contractor's Name: _____

Street Address: _____

City/Zip: _____

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	<input checked="" type="checkbox"/>		
On quality of work	<input checked="" type="checkbox"/>		
On starting when promised	<input checked="" type="checkbox"/>		
On completing once started	<input checked="" type="checkbox"/>		
On fixing problems, if any			

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work - Explanation of Problems - Suggestions to Others

HAD A BAD EXPERIENCE WITH ONE CONTRACTOR
NOT MENTIONED ABOVE, TRIBUZZO CONSTRUCTION
OF LAKEWOOD. HE REPLACED THE CHIMNEY LINER
WITH 4", WAS SUPPOSE TO BE 5". HE TAPED A
PIECE OF 5" TO END OF 4". THIS WAS DISCOVERED

Source used to find contractor: BY POMPELLI PLUMBING WHEN THEY
PUT IN THE CENTRAL AIR, THIS
WILL HAVE TO BE REPLACED.

Category of work: windows Siding Contractor: OASIS SUNROOFING

(121)

Gutters

Evaluation of Repair Service Provided by Contractor

In your opinion, was the work satisfactory? yes no see comments

Date of Work: AUGUST 2010

Description of Work: NEW WINDOWS, NEW VINYL SIDING
NEW GUTTERS

Address where work done: _____ (optional)

Name of Company: OASIS SUNROOFING Phone: _____

Contractor's Name: ANDREW SCHMIDT

Street Address: _____

City/Zip: _____

Please rate your contractor/service in making the repair:

	Very Good	Average	Poor
On the bidding process: answering question, discussing repair options, writing the bid	X		
On quality of work	X		
On starting when promised		X	
On completing once started		X	
On fixing problems, if any	X		

Were there unexpected costs (i.e., was "additional" work needed?) yes no

- Had contractor warned you in advance of the possibility? yes no

- Were the costs fair/reasonable? yes no

Comments on Work – Explanation of Problems – Suggestions to Others

OASIS DID AN EXCELLENT JOB. WE'RE VERY
HAPPY WITH ALL OF THE WORK COMPLETED.

Source used to find contractor: ADVERTISEMENT

What was the total cost of work done: 12K.